

FROM: SAC, PHOENIX
SUBJECT: [REDACTED]

CLASSIFIED MESSAGE

REF: 135

DATE

TOP SECRET

ROUTING

1	INTEL	9
2	DFA	10
3	OTEC	11
4	COMMO	12
5	11	13
6	EYO	14
7	RS	15
8		16

TO :

FROM :

ACTION:

INFO :

IN-56552

03A 1-70

TO

INFO

CITE

25X1

TOP SECRET 191151Z CITE [REDACTED]

IMMEDIATE [REDACTED] INFO IMMEDIATE [REDACTED]

REF: [REDACTED]

25X1

25X1
25X1

25X1

1. DATA CLOCK ACCURACY IS MAINTAINED AT PLUS OR MINUS -30 SECS. FOR 12 HOURS. THE CLOCK WAS SET AT ZULU APPROX. 3 HOURS BEFORE TAKE-OFF. ERROR AT POST FLIGHT WAS NOT ACCURATELY CHECKED.

2. SUGGEST THAT TO FIND CLOCK ERROR, USE EXPOSURE (SHUTTER FIRE) WHICH IS 3.84 SECONDS. THE EXPOSURE ACCURACY IS MAINTAINED AT 100 CYCLES, PLUS OR MINUS 5 SECONDS.

TOP SECRET TOR: 191202Z MAY 66

EDD
PH
RP
KB
DB
AF
NM
DJ

TOP SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION